

Nº	Model	Remarks
30	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 27/01/44
38	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 27/01/44
39	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 23/05/44
48	SVT-38	Accepted for repairs at 1. Aseenkorjauskomppania on 01/02/44
65	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 22/01/44
116	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 26/10/43
131	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 01/02/44
143	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 31/03/44
163	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 21/02/44
170	SVT-38	Accepted for repairs at 1. Aseenkorjauskomppania on 16/05/44
186	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 27/03/44. Shipped to Repola.
194	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 18/11/43
199	SVT-38	Accepted for repairs at 1. Aseenkorjauskomppania on 13/11/43 and on 27/01/44
212	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 11/05/44
222	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 11/05/44
226	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 22/11/43
228	SVT-38	Accepted for repairs at 1. Aseenkorjauskomppania on 01/02/44
239	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 24/11/43
257	SVT-38	Accepted for repairs at 1. Aseenkorjauskomppania on 24/11/43 and 07/02/44
262	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 24/01/44
308	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 14/02/44
345	SVT-38	Accepted for repairs at 1. Aseenkorjauskomppania on 26/05/44
365	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 21/02/44
371	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 29/12/43
385	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 02/05/44
398	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 23/05/44
406	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 13/11/43
412	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 02/05/44. Shipped to Repola.
442	SVT-38	Accepted for repairs at 1. Aseenkorjauskomppania on 01/02/44
465	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 23/12/43
466	SVT-38	Accepted for repairs at 1. Aseenkorjauskomppania on 08/05/44
469	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 24/11/43
479	SVT-38	Accepted for repairs at 1. Aseenkorjauskomppania on 08/05/44
494	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 19/11/43
530	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 14/02/44
540	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 02/05/44
556	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 17/05/44
597	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 19/11/43
617	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 01/02/44
659	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 07/11/43
672	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 22/01/44

678	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 01/02/44
705	SVT-38	Accepted for repairs at 1. Aseenkorjauskomppania on 11/05/44
712	SVT-38	Accepted for repairs at 1. Aseenkorjauskomppania on 03/04/44
741	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 17/12/43 and 08/03/44
748	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 01/02/44
751	SVT-38	Accepted for repairs at 1. Aseenkorjauskomppania on 01/02/44
838	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 17/05/44
854	N/A	Belonged to Jalkaväkirykmentti 39 (JR 39) in May 1940.
866	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 04/05/44
870	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 27/01/44
879	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 08/05/44
886	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 17/05/44
927	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 06/11/43
932	SVT-38	Accepted for repairs at 1. Aseenkorjauskomppania on 18/10/43 and 21/03/44
936	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 06/11/43
938	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 14/02/44
951	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 11/05/44
970	SVT-38	Accepted for repairs at 1. Aseenkorjauskomppania on 07/02/44
978	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 31/05/44. Shipped to Repola.
1054	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 22/11/43
1122	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 01/02/44
1132	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 02/05/44. Shipped to Repola.
1138	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 21/03/44
1192	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 08/05/44
1301	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 01/02/44
1352	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 01/02/44
1407	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 06/06/44
1523	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 17/05/44
1604	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 30/10/43
1614	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 26/05/44
1627	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 27/03/44. Shipped to Repola.
1648	N/A	Accepted for inspection at 1. Aseenkorjauskomppania on 19/06/44
1745	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 14/06/44
1753	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 21/03/44
1759	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 10/02/44
1779	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 24/04/44
1852	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 14/02/44
1863	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 01/02/44 and 17/05/1944
1961	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 15/02/44
2012	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 21/02/44
2039	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 14/02/44
2055	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 18/10/43
2128	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 18/11/43
2225	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 21/02/44
2227	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 21/02/44
2290	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 14/02/44
2311	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 04/05/44. Shipped to Repola.
2416	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 26/05/44

2491	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 21/02/44
2650	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 14/01/44
2857	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 20/11/43
2882	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 14/02/44
3208	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 17/02/44
3294	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 14/02/44
3347	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 31/05/44
3437	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 16/06/44
3623	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 22/11/43
3674	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 07/02/44
3681	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 07/11/43
3838	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 21/02/44
3965	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 08/05/44
3983	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 08/05/44
3986	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 31/05/44
3988	N/A	Accepted for inspection at 1. Aseenkorjauskomppania on 25/04/44
4077	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 26/05/44
4105	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 27/03/44
4166	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 06/11/43
4270	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 06/11/43
4318	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 03/06/44
4410	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 18/12/43
4453	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 16/06/44
4512	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 10/01/44
4577	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 18/12/43
4603	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 11/05/44
4793	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 10/01/44
4795	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 24/04/44
4828	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 21/02/44
4884	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 08/05/44
4905	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 07/11/43
5066	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 17/05/44
5166	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 04/05/44. Shipped to Repola.
5183	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 18/03/44
5571	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 06/11/43
5713	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 29/12/43
5870	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 14/02/44
5921	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 27/01/44
6030	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 16/05/44
6414	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 22/11/43
6524	SVT-40	Accepted for repairs at 1. Aseenkorjauskomppania on 28/01/44
7389	N/A	Accepted for repairs at 1. Aseenkorjauskomppania on 31/05/44